



**FORMAT FOR SUBMISSION OF WATER QUALITY MONITORING REPORT**  
**Water Quality Testing Report**

Collection Time : 10:30am  
 Testing Time : 4:00 pm

For the Month of March Year 2024

Name of District Water Quality Laboratory / Division, Bomdila


Sl.No	Name of Water Source	Date of Water Sample Testing	Parameters								
			Turbidity in NTU	pH	Total Hardness CaCo3	Chloride Cl mg/l	Total Iron as Fe mg/l	Nitrate as NO3 mg/l	Fluoride as F mg/l	F/ Chlorine	Bacteriological Test
1	2	3	4	5	6	7	8	9	10	11	12
1	VKV Shergaon	07.03.2024	0.67	7.65	40	17	0.10	1.22	0.26	0.07	Nil

Note:- The sample is found within permissible limit.

*[Signature]*  
 Lab Assistant

*[Signature]*  
 Executive Engineer  
 PHE & WS Division, Bomdila  
 Executive Eng  
 PHE & W/s Division  
 Bomdila (A.P.)

GOVERNMENT OF ARUNACHAL PRADESH  
OFFICE OF THE EXECUTIVE ENGINEER : : PHE & WS DIVISION, BOMDILA.



No. EEB/PHE/Sch-99/Vol-I/2023-24/ 277

Dated Bomdila the 8<sup>th</sup> March' 2024

The Principal,  
Vivekananda Kendra Vidyalaya School,  
Shergaon.

Sub: Submission of Water Quality Report .


Ref: Yr. Ltr. No. VKV/SGN/2/23-24, Dtd. 06/03/2024

Sir,

In response to reference letter No. cited above, please find enclosed herewith the water quality testing report of water supplied to your school please.

Encl : As Stated Above.

Yours faithfully,

  
Executive Engineer  
PHE & WS Division  
Bomdila

17/03/2024 11:30:00

**GOVERNMENT OF ARUNACHAL PRADESH**  
**OFFICE OF THE EXECUTIVE ENGINEER: P.H.E. & W.S DIVISION**  
**::BOMDILA ::**




**WATER QUALITY MONITORING & SURVEILLANCE**  
**CERTIFICATE**

*This is to certify that the water sample received from*  
*VIVEKANANDA KENDRA VIDYALAYA, SHERGAON on dtd. 07.03.2024 has*  
*undergone analysis for 9 (nine) parameters. The results indicate that the sample falls*  
*within the acceptable limits.*

Date :-

Place:- Bomdila

  
Executive Engineer,  
PHE & WS Division, Bomdila  
8/3/2024

08/03/2024 12:08